

I.C.R. W.U.A. Monthly Operator Notes
January 24, 2016

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line.
24 fiberglass line indicators are needed @ \$40ea. approximately 1hr each for
installation.

A new windmill has been erected where the new well was drilled next to the easement
road. We have been fenced out of the very end of the easement road just before the road
ends above the creek.

Found a bad meter during the meter reads in TRR meter has been replaced. Manufacture
date on the meter 2/11/13 unsure if meter is under warranty, will check with Rep.

Received a call for a possible water leak on War Bonnet (ICR) area was checked and
nothing was found

New spool piece for Molly Way boost station was ordered and should be here sometime
in February

Received and installed 2 new chlorine pumps for the #1 ICR well and for TRR #1

Meter reads went well this month

Monthly samples were collected and delivered to the lab. (No issues)
Also we will be taking alkalinity, TDS and hardness samples to the lab. for CCR update.

All equipment is working properly at this time with the exception of the Molly Way
program issue