

I.C.R. W.U.A. Monthly Operator Notes
October 2018

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our lines.

All new radio read meters are installed with the exception of the well meters, they have been ordered

First reads with the new system went very good 2 meters were identified as having mismatched EIN #'s

26 customer side leak alarms were detected and 24 customers were contacted the other 2 were not home both times we stopped at the residence

Well call orders have been changed at TRR well field for slow season

2 meter installs required the help of an excavating contractor (Norco)

Valve exercised program should be completed by the end of Nov.
per BMP's

Hydrant leak detection have been completed 2 were found not seated all the way and fixed

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time

