

I.C.R. W.U.A. Monthly Operator Notes
February 23, 2016

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line

ADEQ performed inspections on both systems 2/10/16 the only issue found was we did not have 5 in. of the support ring showing on the W.C. and Cooper Morgan tanks. This issue was taken care of and pictures emailed to the inspector.

Empire was called out to the Molly Way generator to look at a coolant leak they filled the coolant reservoir and cleared the alarm

2 bad meters were replaced 5/8 on Forked Trail (ICR) and the 2' landscape meter (TRR)

3 meter installs 2 (TRR) 1 (W.C.) 3 more are to be installed this week all (TRR)

After checking the meters on the (commercial/landscape) list 4 irrigation meters were found that could not be checked

The landscape meter on Stella is fine, the water is off.

Meter reads went well this month

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way program issue

