

I.C.R. W.U.A. Monthly Operator Notes
September 27, 2016

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line

The needle valve on the deep well control valve on ICR #1 has been repaired and
reinstalled

Inline filters have been installed on the control valves for both ICR wells

ICR well #1 had some electrical issues, Envirotech was called and replaced the motor
saver and starter switch

Norco repaired a leak on Almosta Ranch Road

Well call order has been changed at the TRR well field, per Bill

Replaced pressure switch at Molly Way boost station

3 meters install 2 (TRR) 1 (ICR)

Yearly valve exercise program has started

Weed abatement is on-going

Meter reads went well this month

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way
program issue