

I.C.R. W.U.A. Monthly Operator Notes
October 2017

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line.

Both generators have been serviced for the year, it was recommended that the batteries be replaced on the Molly Way unit

The hydro. (air over water) tank is on line and working properly at the Molly Way boost station, this should decrease power usage

Whispering Canyon boost station has been blue staked

TRR well call order has been changed (#1,#3, #2)

(6) Meter installs this month (6) TRR (1) defective meter was found and replaced (ICR)

Numerous call outs for the Cooper Morgan boost station APS appeared to be the issue, VFD's were reprogramed and a data logger will be installed on the meter

All heaters are on for the winter at all sites

Responded to two customer complaints for high usage (landscape issues)

Repaired a leak on Mescal Canyon (meter setter leaking and changed out)

Hydrant leak detection completed for the year, found 1 leaking on Almost Ranch Rd.

Valve exercise program is on-going

Meter reads went well this month, the Board may want to revisit the radio read system

Monthly and the first required quarterly DBP's samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way program issue and the pump motor issue at Cooper Morgan

