

I.C.R. W.U.A. Monthly Operator Notes  
August 29, 2017

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line.

Enviro-Tech has started work on the pressure tank, having issues with getting parts should be complete in September

A fire hydrant was hit and knocked over on Double Adobe (TRR), no water loss, Steve Norris repaired the hydrant

The #2 boost pump motor at Cooper Morgan boost station needs the seals replaced, I would suggest that we order a backup motor to have on site these are over 10 yrs. old

All meter verifications have been completed for the year, 59 total, no meters out of compliance

(7) Meter installs this month (5) TRR (1) ICR (1) Whispering Canyon (2) defective meters were found and replaced in TRR

Checked on a water complaint on Sandia Ln. (TRR), lines were flushed.

Weed abatement is ongoing

Meter reads went well this month.

Monthly and samples were collected and delivered to the lab. (No issues)

We had an exceedance on one of our yearly samples in TRR (TTHM/ mcl .08 sample result .109) ADEQ has required us to sample quarterly for a year at this site

All equipment is working properly at this time with the exception of the Molly Way program issue and the pump motor issue at Cooper Morgan

