

I.C.R. W.U.A. Monthly Operator Notes  
December 2018

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our lines

Waiting on Fortiline to fabricate the spools for the new well meters we will install them when the spools are complete

Assisted LP excavating with a 6" hot tap in the Ranch Compound

Emergency call out at Molly Way during the Christmas Holiday it appears LP excavating forgot to turn off and drain the hydrant meter and it froze and broke

(5) new meters were installed in TRR and (1) in ICR

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time

