

I.C.R. W.U.A. Monthly Operator Notes
October 6, 2015

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked 2 times this month to ensure no leaks or issues with our
line

Molly Way VFD was replaced and programmed the first week of Sept. It seems to be
working correctly

Meter verifications are complete for the year (50), Derek thinks that 15 were out of the
3% range

Valve exercise program has started for the year, we have completed over half so far

Hydrant leak detection should be completed by the first week of Oct., so far 3 in ICR
and 1 in TRR with slight leaks

1 meter install and 1 meter replacement in TRR

The well control valve at ICR #1 was taken apart and cleaned

Weed abatement is coming to an end for the year

Meter reads went well this month

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way
program issue

