

I.C.R. W.U.A. Monthly Operator Notes
April 26, 2016

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line

Well meter program is ongoing, both ICR #1 and TRR #1 are back and reinstalled.

ICR #1 is still off line while we make repairs to the chlorine injection system.

Switch failure on ICR #2 caused the Magner tank to overflow on 4/13 the issue was corrected and is functioning correctly.

Cooper Morgan boost station had problems with telemetry, Enviro –Tech was called, the issue was with the PLC for the call order for the wells.

4 new meter installs all in TRR

I am working on the 2015 CCR, It should be completed soon

Meter reads went well this month the new system seems to be working good

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way program issue

