

I.C.R. W.U.A. Monthly Operator Notes
April 28, 2015

Molly Way was flushed twice and the fire pumps exercised. During one event we had a VFD fault on pump #3. Enviro-Tech will be troubleshooting this on their next visit.

The easement road was checked to ensure no leaks or issues with our line

Cooper Morgan boost pump seals were replaced by Enviro Tech

Tank divers cleaned and videoed Whispering Canyon and Cooper Morgan tanks on 4/1.
We have the C.D.'s and are waiting for their report.

Valve can project is still in the works.

We're still having trouble with the Flo-tronics rep getting a hold of us to do repairs on the Molly Way PLC. After several phone calls with no response it is my opinion we should hire a computer programmer to reprogram the system.

Two meter installs this month, both in I.C.R. One standard and one non-standard.

Meter reads went well this month

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the above mentioned.

