

I.C.R. W.U.A. Monthly Operator Notes
December 2017

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line.

The generators radiator at the Molly Way boost station failed on New Year day...
(Happy New Year) the parts are on order and it will be repaired ASAP

Found and replaced (3) bad meters during meter reads 2 (TRR) 1(ICR)

(1)New meter install (TRR)

Meter reads went well this month

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way
program issue

