

I.C.R. W.U.A. Monthly Operator Notes
November 2017

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line.

The generator at the Cooper Morgan boost station had a bad “mother board” it has been replaced and is cycling normal

A data logger was installed at the Cooper Morgan boost station on the APS meter for six days to see if there were any power spikes/drops, it appears that the APS feed is normal

Whispering Canyon boost station has been blue staked

ICR well #1 is back on-line as the primary #2 as back-up per Bills request

Verified 5 meters after complaints at the meeting last month 4 were fine 1 was out 5%

Steve Norris excavated and replaced a bad ARV at the end of War Paint in ICR

Installed 3 new meters (2) TRR (1) ICR, replaced a leaking meter in ICR

Valve exercise program is complete for the year

Meter reads went well this month, obtained pricing for radio read meters (Tom distributed them to the Board)

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way program issue

